




Typical Grease Interceptor – Appendix A



STARK COUNTY SANITARY ENGINEERING

Notes:

Grease interceptor to be constructed in accordance with ASTM C1613-10.

Bottom outlet required as shown to prevent removal of an internal outlet tee.

Clean-outs must be installed to facilitate blockage removal in either direction.